

Inspection date: / /

This form is to be completed with reference to the Division 5 Asb

Name and address of Department workplace: **TEMPLETON PRIMARY SCHOOL**

Updated Register signed off by:

**Asbestos Coordinator** and

Building / Site Location	Action Rating	SAMS Room Number/s	Room Description	Asbestos Containing Materials (ACM) Description	Surface (e.g. ceilings, walls)	Condition of ACM at Audit
BLOCK A		3	STORE	AC SHEETING	WALLS	GOOD
		3	STORE	AC SHEETING	CEILING	GOOD
		4	PLANT ROOM	AC SHEETING	WALLS	REQUIRES-ATTENTION
		4	PLANT ROOM	AC SHEETING	CEILING	GOOD
		6	STORE	PRESUMED	FIRE SAFE	
		6	STORE	VINYL FLOOR TILES	VINYL FLOOR TILES	GOOD
		8	STORE	VINYL FLOOR TILES	VINYL FLOOR TILES	GOOD
		13	LIBRARY	AC SHEETING	LOWER WALLS	GOOD
		19	PLANT ROOM	AC SHEETING	WALLS	GOOD
		19	PLANT ROOM	CEMENT PIPE	HEATER FLUE	REQUIRES ATTENTION

Building / Site Location	Action Rating	SAMS Room Number/s	Room Description	Asbestos Containing Materials (ACM) Description	Surface (e.g. ceilings, walls)	Condition of ACM at Audit
		19	PLANT ROOM	AC SHEETING	CEILING	GOOD
		20	PASSAGE	VINYL FLOOR TILES	VINYL FLOOR TILES	VINYL FLOOR TILES
		22	FIRST AID	VINYL FLOOR TILES	VINYL FLOOR TILES	VINYL FLOOR TILES
		24	STORE	AC SHEETING	INFILL PANEL	NO ACCESS (VOID)
		25	PORCH	AC SHEETING	CEILING	GOOD
		26	PLANT ROOM	AC SHEETING	WALLS	REQUIRES ATTENTION
		<del>26</del>	<del>PLANT ROOM</del>	<del>AC SHEETING</del>	<del>CEILING</del>	<del>REQUIRES ATTENTION</del>
		<del>27</del>	<del>CLEANER</del>	<del>AC SHEETING</del>	<del>WALLS</del>	<del>REQUIRES ATTENTION</del>
		<del>27</del>	<del>CLEANER</del>	<del>AC SHEETING</del>	<del>CEILING</del>	<del>GOOD</del>

Building / Site Location	Action Rating	SAMS Room Number/s	Room Description	Asbestos Containing Materials (ACM) Description	Surface (e.g. ceilings, walls)	Condition of ACM at Audit
			CLEANER	AC SHEETING	DEBRIS IN CEILING SPACE	NO ACCESS TO CEILING
		28	STORE	VINYL FLOOR TILES	VINYL FLOOR TILES	GOOD
		30	STORE	VINYL FLOOR TILES	VINYL FLOOR TILES	GOOD
		31	ARTCRAFT	VINYL FLOOR TILES	VINYL FLOOR TILES	GOOD
		81	FOYER	AC SHEETING	ELECTRICAL SWITCHBOARD WALLS	
			EXTERNAL	AC SHEETING	EAVES	GOOD
COVERED WAY – BLOCKS 12 & 13		72	COVERED WAY	AC SHEETING	CEILING	GOOD
		74	COVERED WAY	AC SHEETING	CEILING	GOOD
GALLERIES BLOCKS 14 & 15		75	GALLERY	AC SHEETING	CEILING	GOOD
		77	GALLERY	AC SHEETING	CEILING	GOOD
		170	GALLERY	AC SHEETING	CEILING	GOOD
MUSIC			EXTERNAL		WINDOW MASTIC	
PORTABLE 3961		154	CLASSROOM	AC SHEETING	CEILING	GOOD

Building / Site Location	Action Rating	SAMS Room Number/s	Room Description	Asbestos Containing Materials (ACM) Description	Surface (e.g. ceilings, walls)	Condition of ACM at Audit
		155	STORE	AC SHEETING	CEILING	GOOD
		156	WITHDRAWAL	AC SHEETING	CEILING	GOOD
		157	CLASSROOM	AC SHEETING	CEILING	GOOD
			EXTERNAL	AC SHEETING	EAVES	GOOD
			EXTERNAL	AC SHEETING	PORCH CEILING	GOOD
			EXTERNAL	MASTIC	WINDOW MASTIC	GOOD
PORTABLE 4025			EXTERNAL	MASTIC	WINDOW MASTIC	GOOD
PORTABLE 4026			EXTERNAL	MASTIC	WINDOW MASTIC	GOOD
PORTABLE 4029			EXTERNAL	MASTIC	WINDOW MASTIC	GOOD
PORTABLE 5431			EXTERNAL	MASTIC	WINDOW MASTIC	GOOD
PORTABLE 7962			EXTERNAL	AC SHEETING	EAVES	GOOD

**Asbestos Audit Report** dated: **31/03/2016**

Inspection conducted by:

**Health and Safety Representative:**

Current Condition of ACM	Further Action / Comment	Date of Removal of Asbestos Item/s	Re-inspection date
	<del>EXPOSED EDGE</del>	<del>REMOVED 11/01/2020</del>	
	UNPAINTED, RECOMMEND ENCAPSULATION		

Current Condition of ACM	Further Action / Comment	Date of Removal of Asbestos Item/s	Re-inspection date
	COVERED WITH CARPET		
	EXPOSED EDGES		
	<del>EXPOSED EDGES</del>		
	<del>EXPOSED EDGE</del>	REMOVED 11/01/2020	
		REMOVED 11/01/2020	

Current Condition of ACM	Further Action / Comment	Date of Removal of Asbestos Item/s	Re-inspection date
		REMOVED 11/01/2020	

# Human Resources **Asbestos Register**

Current Condition of ACM	Further Action / Comment	Date of Removal of Asbestos Item/s	Re-inspection date